

□□□□□□□□□□□□□□

Inspection Report

Report No.: XYD-130703
Supplier : XY-GLOBAL







Inspection Date: 10th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130703 Item No.XY-956400	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-956400	800PCS	5% inspection	0pcs	No failure	800pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380
規格	±0.01mm
數量	50000
MOQ	50000
公差	±0.01mm
表面處理	噴砂
檢驗標準	ISO 9001
包裝	100個/箱
交期	20-25天
備註	CNC加工
1.Name	OEM
2.cnc	
3.ADC12 A380	
4.公差	±0.01mm
5.數量	10000
6.OEM	
7.交期	25-30天
8.檢驗標準	ISO 9001
9.包裝	
10.	
11.ISO 9001	
12.	
13.	
14.	
15.	
16.	
17.	
18.	
19.	
20.	
21.	
22.	
23.	
24.	
25.	
26.	
27.	
28.	
29.	
30.	
31.	
32.	
33.	
34.	
35.	
36.	
37.	
38.	
39.	
40.	
41.	
42.	
43.	
44.	
45.	
46.	
47.	
48.	
49.	
50.	
51.	
52.	
53.	
54.	
55.	
56.	
57.	
58.	
59.	
60.	
61.	
62.	
63.	
64.	
65.	
66.	
67.	
68.	
69.	
70.	
71.	
72.	
73.	
74.	
75.	
76.	
77.	
78.	
79.	
80.	
81.	
82.	
83.	
84.	
85.	
86.	
87.	
88.	
89.	
90.	
91.	
92.	
93.	
94.	
95.	
96.	
97.	
98.	
99.	
100.	

