

Inspection Report

Report No.: XYK-131017
Supplier : XY-GLOBAL







Inspection Date: 11th Nov-, 2013
Inspector:ALEX

Inspection only for: PO . XYK-131017 Item No.XY-MST-089	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-089	95000PCS	0.1% inspection	0pcs	No failure	95000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

