

**Inspection Report**

**Report No.:** XYA-131009  
**Supplier :** XY-GLOBAL

**Inspection Date:**15<sup>th</sup> Nov-, 2013  
**Inspector:**ALEX

<b>Inspection only for:</b> PO . XYA-131009 Item No.XY-MST-074	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-074	50000PCS	1% inspection	0pcs	No failure	50000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	鋼 鋁切削加工品 鋼 鋁切削加工品 CNC 鋼 鋁切削加工品 CNC 鋼 鋁切削加工品 CNC
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
形状	
寸法	
公差	+/-0.01
表面処理	T / T 50 T / T 50 T / T
検査	
備考	
1.Name	cnc
2.Process	
	AL6061 AL6065 AL6063 AL7075
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1	10 ISO
2	
3	kindls available
4	
5	
6	
7	
	&NBSP;
	ISO9001