

Inspection Report

Report No.: XYD-130813
Supplier : XY-GLOBAL

Inspection Date:10th- Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYD-130813 Item No.1400038	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400038	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	品名 CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 &NBSP; SUS304 SUS303 SUS316
形状	
仕様	
加工	CNC加工品
加工	gague加工品
加工	
公差	+/-0.01
公差	T / T 50 T / T 50 T / T
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name	cnc加工品
2.Process	
	AL6061 AL6065 AL6063 AL7075
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
品名	
1.	10 ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
品名	
	&NBSP;
	ISO9001