

Inspection Report







Report No.: XYSL-150619
 Supplier : XY-GLOBAL

Inspection Date: 25th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150619 Item No. XY31XL017	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL017	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

00	0000 00000000000000000000000000000000 00000000000000000000 00000000000000000000
00	AL6061 AL6065AL6063AL7075 SUS303SUS304 SUS316POM
00	00 000000
0000	0 0000 000 000 000 000 000 000000
00	00 000000000000
0000	00 00000 000 000000 000 000000000000000000 00
0000	00 0000 00000000000000000000 00000 00000 0000000000 0000000000000000 00000000 00
00000	00
00V00	+ V-0.01 00
00	TVT 50%00000050 %t V T 0000; 00000
0000	00 0000000000000000 00000 000 000000000000 000 00000000
0000	0000 00 000000 000000 0000 0000 000000000000000000
00	00 00
00	20-25 0 TVT 50%000
0000	00 0000
1.000 0000 OEM 000000	
2.Process 0000cnc 00	
3.Material: AL6061 AL6065AL6063AL7075 POM 0	
4.Surface 0000 000 00000000 0000	
5.Tolerance 00 + V-0.01 00	
6.00000 100%00	
7.Specification: OEM 000000000000	
8.00000000 25-30 00000000	
9.0000 cnc 000000000000 000000 0000 000000	
10.0000 000 0000 000000 0000	
11.0000 ISO 9001	
00000	
1.10 000000 ISO 00	
2.00000000	
3.00 kinds 00000000000000	
4.000000000000	
5.00000000	
6.000000	
7.000000000000	
000000	
000000000000 00000	
000000000000 00000	
000000000000 ISO9001	
000000000000 00000000	
00 OEM 00000000	

Safety is our serious job for our worker and engineer team



[oem](#) □□□□□□