

Inspection Report

Report No.: XYFD-130804
Supplier : XY-GLOBAL

Inspection Date: 3th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYFD-130804 Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

00	00 00000000000000000000 000000000000000000000000 0000000000 0000000000
00	AL6061 AL6065AL6063AL7075 SUS304 SUS316 SUS303 POM
00	00000000
0000	0000 000 000 000 000 000000
00	000000000000
0000	00000000 000 0000000 00000000 00000000000 000000
0000	0000000 000000000000 000000000000 000000 0000000 000000 0000000000000 00000 0000000 00000
000000	00
00V00	+ V-0.01 00
00	TVT 50%00000050 %t V T 00000; 000000
0000	000000000000000000000000000000 0000 0000 00000000000000000000 0
0000	00000 0000000 00000 0000 0000 0000000000000000 00000
00	00000
00	20-25 00 TVT 50%0000
0000	00000000
1.000 00000 OEM 00000000	
2.Process 00000cnc 00	
3.Material: AL6061 AL6065AL6063AL7075 POM	
4.Surface 00000 0000 0000000000 00000	
5.Tolerance 00 + V-0.01 00	
6.000000 100%00	
7.Specification: OEM 00000000000000	
8.0000000000 25-30 0000000000	
9.0000 cnc 00000000000000 0000000 0000 0000000	
10.0000 0000 00000 0000000 00000	
11.0000 ISO 9001	
00 00	
1.10 0000000 ISO 00	
2.00000000	
3.00 kinds 0000000000000000	
4.00000000000000	
5.0000000000	
6.000000	
7.00000000000000	
00 00	
00000000000000 00000	
000000000000 00000	
000000000000 ISO9001	
000000000000 0000000000	
00 OEM 00000000	

