

**Inspection Report**







Report No.: XYFA-130802  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup> Sep-, 2013  
 Inspector: LEO

Inspection only for: PO . XYFA-130802      Item No.400-01-056	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-056	100000pcs	100% inspection	0pcs	No failure	100000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

品名	品名 加工品
品名	品名 ADC12 A380
品名	品名 加工品
品名	品名 加工品
品名	品名 加工品
品名	CNC 加工品
品名	品名 gague 加工品
MOQ	品名
公差	+/- 0.01
公差	T / T 50 T / T
品名	CNC 加工品
品名	品名 加工品
品名	品名 加工品
品名	20 25 T / T 50
品名	品名 加工品
1.Name	OEM 加工品
2.Process	CNC 加工品
3.Material	ADC12 A380
4.Surface	nickle 加工品
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM serice 加工品
8.	25 30
9.	accessoried 加工品
10.	Austrial EU
11.	ISO 9001
品名	品名 加工品
ISO	1. 10
2.	品名 加工品
3. sureface	finishment kinds available
品名	4. 品名
5.	品名
品名	6. 品名
7.	品名 加工品
品名	品名 加工品
品名	品名 加工品
品名	ISO9001
品名	品名 加工品
OEM	加工品