

□□□□□□□□□□□□□□□□□□□□□□□□□□□□□□

### Inspection Report







**Report No.:** XYS-130907  
**Supplier :** XY-GLOBAL

**Inspection Date:** 4<sup>th</sup> Oct, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130907 Item No.100097	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100097	<b>2000PCS</b>	5% inspection	0pcs	No failure	2000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	铝合金 CNC加工零件 OEM
规格	ADC12 A380
数量	10000
用途	汽车零部件
材料	ADC12
工艺	CNC 加工
表面处理	阳极氧化
公差	±0.01
交期	15天
MOQ	1000
包装	纸箱
认证	ISO 9001
其他	
1.Name	铝合金 CNC加工零件 OEM
2.Process	CNC 加工
3.规格	ADC12 A380
4.Surface	阳极氧化
5.Tolerance	±0.01
6.数量	10000
7.Specification	OEM
8.交期	15天
9.表面处理	阳极氧化
10.认证	ISO 9001
11.&nbsp;	
ISO	ISO 9001
2.	
3 surface	阳极氧化
4.	
5.	
6.	
7.	
ISO	ISO 9001
OEM	