

**Inspection Report**

Report No.: XYBA-141112  
 Supplier : XY-GLOBAL

Inspection Date: 12<sup>th</sup> Dec., 2014  
 Inspector:LEO

Inspection only for: PO . XYBA-141112    Item No. XY21ZC029	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC029	10000Pcs	7% inspection	Opes	No failure	10000Pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC 部品
品番	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
材質	
仕様	
公差	+/- 0.01
MOQ	
納期	T / T 50
加工方法	CNC
表面処理	nickle
1. Name	OEM CNC
2. Process	CNC
3. Material	AL6061 AL6065 AL6063 AL7075 POM
4. Surface	nickle
5. Tolerance	+/- 0.01
6. Quantity	100
7. Specification	OEM service
8. Lead time	25-30
9. Accessory	accessories
10. Standard	Austrial EU
11. ISO	ISO 9001
ISO	1. 10
2. Surface	finishment kinds available
3. Surface	finishment kinds available
4. Quantity	
5. Lead time	
6. Accessory	
7. Standard	
8. ISO	ISO 9001
9. Lead time	
10. Accessory	
11. Standard	OEM