

**Inspection Report**

Report No.: XYAN-150418  
 Supplier : XY-GLOBAL

Inspection Date: 22<sup>th</sup> May-, 2015  
 Inspector: LEO

Inspection only for: PO . XYAN-150418    Item No. XY21ZC084	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC084	12000pcs	7% inspection	Opcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	CNC加工 機械部品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
形状	図面通り
加工	機械加工
公差	CNC加工 機械部品
表面処理	機械加工後、gaugeチェック、バリ取り、油取り
MOQ	100個
精度	+/- 0.01mm
納期	T / T 50% / T / T 100%
加工	CNC加工 機械部品
品質保証	品質保証書発行
送料	送料別
検閲	20~25 T / T 50%
加工	CNC加工 機械部品
1. Name 機械部品 OEM CNC加工	
2. Process 機械加工 CNC加工	
3. Material AL6061 AL6065 AL6063 AL7075 POM	
4. Surface 機械加工後、nickle	
5. Tolerance +/- 0.01mm	
6. MOQ 100個	
7. Specification OEM service	
8. 検閲 25~30%	
9. CNC加工 機械部品 accessories	
10. 品質保証書 Austrian EU	
11. ISO 9001	
品質保証	
ISO 1. 10	
2. 検閲	
3. surface finishment kinds available	
4. 検閲	
5. 検閲	
6. 検閲	
7. 検閲	
品質保証	
CNC加工 機械部品	
CNC加工 機械部品	
CNC加工 ISO9001	
CNC加工 機械部品	
CNC加工 OEM	

Safety is our serious job for our worker and engineer team

