

Inspection Report

Report No.: XYBA-140908
 Supplier : XY-GLOBAL

Inspection Date: 1st Oct-, 2014
 Inspector: LEO

Inspection only for: PO . XYBA-140908 Item No. XY21ZC005	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC005	500PCS	7% inspection	0pcs	No failure	500pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000
⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000
⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000
㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000
㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000
㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺						
NO	XYBA-140908	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005	XY21ZC005
A	30.00	0.200	0.200	30.00	0.000	0.000
T	150.00	0.200	0.200	150.00	0.000	0.000
D	2.000	0.200	0.200	2.000	0.000	0.000

5. Product :

6. Inspection report:

