

Inspection Report

Report No.: XYBA-140906
 Supplier : XY-GLOBAL

Inspection Date: 1th Oct, 2014
 Inspector: LEO

Inspection only for: PO . XYBA-140906 Item No. XY21ZC004	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC004	800PCS	7% inspection	0pcs	No failure	800pcs







Appearance Inspection :
 No failure.

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

品名	CNC 部品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
仕様	
数量	
公差	CNC 公差
表面処理	gague
MOQ	
公差	+/- 0.01
リードタイム	T / T 50
加工機	CNC
検査機	CNC
公差	
公差	20-25 T / T 50
公差	CNC
1.Name OEM CNC	
2.Process CNC	
3.Material AL6061 AL6065 AL6063 AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6.数量 100	
7.Specification OEM service	
8.公差 25 30	
9.CNC accessoried	
10.Austrial EU	
11.ISO 9001	
ISO 1. 10	
2. surface finishment kinds available	
4.	
5.	
6.	
7.	
CNC	
CNC	
CNC ISO9001	
CNC	
CNC OEM	