

Inspection Report

Report No.: XYDA-140512
 Supplier : XY-GLOBAL

Inspection Date: 10th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYDA-140512 Item No.1400872	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1400872	6000PCS	1% inspection	0pcs	No failure	6000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

製品名	製品名 製品仕様書に記載されている通り 製品名OEM製品仕様書に記載されている通り
材料	材料ADC12/A380
表面処理	表面処理
公差	公差
加工方法	CNC加工
MOQ	MOQ
寸法	+/- 0.01
納期	T / T 50
加工精度	CNC加工
表面処理	表面処理
寸法	20-25 T / T 50
表面処理	表面処理
1.Name製品名OEM製品仕様書に記載されている通り	
2.Process製品仕様書に記載されている通りCNC加工	
3.Material材料ADC12/A380	
4.Surface表面処理nickle製品仕様書に記載されている通り	
5.Tolerance公差 +/- 0.01	
6. MOQ	
7.SpecificationOEM製品仕様書に記載されている通り	
8. 寸法	
9. 表面処理	
10. 加工精度	
11. ISO 9001	
ISO 9001	
2. 表面処理	
3. sureface finishment kinds available	
4. 寸法	
5. 公差	
6. 納期	
7. 加工精度	
8. 表面処理	
9. 寸法	
10. 加工精度	
11. ISO9001	
OEM製品仕様書に記載されている通り	