

□□□□□□□□□□□□□□□□

Inspection Report

Report No.: 130925

Inspection Date: 25th Sep 2013

Supplier :

Inspector: Ken Tung

Inspection only for: Item No. ARM00039	Inspection Result: PASS
---	----------------------------

Description	Finished Qty	Sample Size	Defect Found	Defects Description	Acceptable Qty
ARM	1000sets	100%	12pcs	12pcs poor painting	1000pcs















Appearance Inspection :
No failure,
12pcs poor painting

Dimension Inspection:
No failure , below measurement report for reference.

Leakage Test:
No failure

Inspection Summary
The inspection sample plan are follow AQL , 12pcs poor painting The result of inspection is acceptable.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4. Item number
	
5. Product	6. Product
	
7 Customer No.	8. Product
	
9. Defect-Poor painting	10. Defect-Poor painting
	
11. Test	12. Test
	
13. Carton	14. Loading

