

Inspection Report

Report No.: XYK-130819  
 Supplier : XY-GLOBAL

Inspection Date:14<sup>th</sup> Sep-, 2013  
 Inspector:LEO

Inspection only for: PO . XYK-130819    Item No.1402230	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1402230	8000PCS	1% inspection	0pcs	No failure	8000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
1. Packing	2. Product.
3. Product:	4. Product:
5. Product :	6. Product:

	<b>CNC</b>
Material	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
Process	CNC
MOQ	100
Tolerance	+/- 0.01
Lead Time	T / T 50
1.Name	OEM CNC
2.Process	CNC
3.	AL6061 AL6065 AL6063 AL7075 POM
4.Surface	nickle
5.Tolerance	+/- 0.01
6.	100
7.Specification	OEM
8.	25-30
9.	accessories
10.	Austrial EU
11.	ISO 9001
ISO	10
2.	
3	sureface finishment kinds available
	4
5	
	6
7	
CNC	
CNC	
CNC	ISO9001
CNC	
CNC	OEM