

Inspection Report

Report No.: XYS-130723
Supplier : XY-GLOBAL

Inspection Date:15th Aug, 2013
Inspector: Leo

Inspection only for: PO . XYS-130723 Item No.XY-300985	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-300985	500PCS	5% inspection	0pcs	No failure	500pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

...	... OEM ...
...	ADC12 A380
...	...
...	...
...	CNC ... CNC
...	...
MOQ	...
...	+/- 0.01mm
...	T / T 50 ... 50 T / T
...	CNC ... CNC
...	...
...	...
...	20-25 T / T 50
...	...
1. OEM	
2. CNC	
3. Material ADC12 A380	
4. ...	
5. ±0.01mm	
6. 100	
7. OEM service	
8. 25-30	
9. ...	
10. Austria EU	
11. ISO 9001	
...	
1. ISO 10	
2. ...	
4. ...	
5. ...	
6. ...	
7. ...	
...	
...	
...	ISO9001
...	...
...	OEM

... Oem ...