

Inspection Report







Report No.: XYN-140619
Supplier : XY-GLOBAL

Inspection Date: 14th July, 2014
Inspector: Leo

Inspection only for: PO . XYN-140619 Item No.209543	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
209543	9000PCS	1% inspection	0pcs	No failure	9000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

	CNC CNC CNC CNC CNC CNC CNC CNC CNC
	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
	CNC CNC CNC CNC CNC
	gague
MOQ	
/	+/- 0.01
	T / T 50 50 T / T;
	CNC CNC CNC CNC CNC CNC CNC CNC
	20-25 T / T 50
	CNC
1.Name OEM CNC	
2.Process CNC	
3. AL6061 AL6065 AL6063 AL7075 POM	
4.Surface nickle	
5.Tolerance +/- 0.01	
6 100	
7.Specification OEM	
8 25-30	
9 CNC accessoried	
10 Austrial EU	
11 ISO 9001	
ISO 1 10	
2	
3 sureface finishment kinds abailable	
5	
7	
CNC 	
CNC	
CNC ISO9001	
CNC	
CNC OEM	