

**Inspection Report**

**Report No.:** XYBA-140901  
**Supplier :** XY-GLOBAL

**Inspection Date:** 18<sup>th</sup> Oct., 2014  
**Inspector:** LEO

Inspection only for: PO . XYBA-140901      Item No. XY21ZC001	<b>Inspection Result:</b> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC001	1000PCS	7% inspection	0pcs	No failure	1000pcs





**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

Company Name	CNC Manufacturing Solutions
Material	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
Surface Treatment	nickle
Tolerance	+/- 0.01
MOQ	
Lead Time	T / T 50
Payment Terms	
Quality Control	ISO 9001
Other Services	accessories
1. Name	OEM CNC
2. Process	CNC
3. Material	AL6061 AL6065 AL6063 AL7075 POM
4. Surface	nickle
5. Tolerance	+/- 0.01
6. Lead Time	100
7. Specification	OEM service
8. Quantity	25 30
9. Additional Services	accessories
10. Certifications	Austrial EU
11. ISO	9001
1. ISO	10
2. Surface	
3. Surface Finish	kindls available
4. Lead Time	
5. Quantity	
6. Price	
7. Payment	
8. Quality	
9. CNC	
10. CNC	
11. CNC	ISO9001
12. CNC	
13. CNC	OEM