

Inspection Report

Report No.: XYL-150725
 Supplier : XY-GLOBAL

Inspection Date: 14th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150725 Item No. XY11LM025	<u>Inspection Result:</u> PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM025	18000PCS	1% inspection	0pcs	No failure	18000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	部品 部品名
品番	部品名 ADC12 A380
仕様	部品名
材質	部 部品名
加工	部 部品名
加工	CNC 部品名 CNC
加工	部 部品名 gague 部品名
MOQ	部
公差	+/- 0.01
公差	T / T 50 部品名 50 T / T 部品名
加工	CNC 部品名 CNC 部品名
加工	部品名 部品名
加工	部
加工	20 25 T / T 50
加工	部 部品名
1.Name 部品名 OEM 部品名	
2.Process 部品名 CNC	
3.Material 部品名 ADC12 A380	
4.Surface 部品名 部品名	
5.Tolerance +/- 0.01	
6 部品名 100	
7.Specification 部品名 OEM serice	
8 部品名 25-30	
9 部品名 accessoried	
10 部品名 Austrial EU	
11. 部品名 ISO 9001	
部品名	
1 部品名 ISO 10	
2 部品名	
3 surface finishment kinds available	
4 部品名	
5 部品名	
6 部品名	
7 部品名	
部品名	
部品名 部品名	
部品名 部品名	
部品名 ISO9001	
部品名 部品名	
部品名 OEM 部品名	



High qualified surface treatment can make your parts perfect !!!

