

Inspection Report

Report No.: XYL-150716
 Supplier : XY-GLOBAL




Inspection Date: 27th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150716 Item No. XY11LM016	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM016	7000PCS	1% inspection	0pcs	No failure	7000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. Report:

品名	品名 部品名 OEM
仕様	仕様 ADC12 A380
材質	材質 部品名
加工	加工 部品名
公差	公差 部品名
表面	表面 部品名
MOQ	MOQ 部品名
公差	公差 +/- 0.01
公差	公差 T / T 50
公差	公差 CNC
公差	公差 部品名
公差	公差 部品名
公差	公差 20 25 T / T 50
公差	公差 部品名
1.Name 部品名 OEM	
2.Process 部品名 CNC	
3.Material 部品名 ADC12 A380	
4.Surface 部品名 部品名	
5.Tolerance +/- 0.01	
6 部品名 100	
7.Specification 部品名 OEM service	
8 部品名 25-30	
9 部品名 accessoried	
10 部品名 Austrial EU	
11. 部品名 ISO 9001	
部品名	
1 部品名 ISO 10	
2 部品名	
3 surface finishment kinds available	
4 部品名	
5 部品名	
6 部品名	
7 部品名	
部品名	
部品名 部品名	
部品名 部品名	
部品名 ISO9001	
部品名 部品名	
部品名 OEM	

Safety is our serious job for our worker and engineer team

