

Inspection Report

Report No.: XYL-150720
 Supplier : XY-GLOBAL

Inspection Date: 5th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150720 Item No. XY11LM020	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM020	11000PCS	1% inspection	0pcs	No failure	11000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



5. Product:	6. Report:
-------------	------------





品名	部品 部品名OEM部品
仕様	ADC12 A380
材質	部品名
加工	加工方法
公差	加工公差
MOQ	MOQ
公差	+/- 0.01
公差	T / T 50
公差	CNC
公差	加工公差
公差	加工公差
公差	20 25 T / T 50
公差	加工公差
1.Name 部品名OEM部品	
2.Process 加工方法CNC	
3.Material 部品ADC12 A380	
4.Surface 加工表面	
5.Tolerance +/- 0.01	
6 部品名100	
7.Specification 加工方法OEM service	
8 部品名25-30	
9 部品名accessoried	
10 部品名Austrial EU	
11. 部品 ISO 9001	
部品名	
1 部品名10	
2 部品名	
3 surface finishment kinds available	
4 部品名	
5 部品名	
6 部品名	
7 部品名	
部品名	
部品名 加工公差	
部品名 加工公差	
部品名 ISO9001	
部品名 加工公差	
部品名 OEM	

Safety is our serious job for our worker and engineer team

