

Inspection Report







Report No.: XYL-150724
 Supplier : XY-GLOBAL

Inspection Date: 12th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150724 Item No. XY11LM024	Inspection Result: PASS
------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM024	18000PCS	1% inspection	Opcs	No failure	18000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	部品 部品名 OEM
仕様	ADC12 A380
材質	部品名
加工	加工
公差	加工
表面	CNC
MOQ	加工
公差	+/- 0.01
公差	T / T 50
公差	CNC
公差	加工
公差	加工
公差	20 25 T / T 50
公差	加工
1.Name 部品名 OEM	
2.Process 加工 CNC	
3.Material 部品名 ADC12 A380	
4.Surface 加工	
5.Tolerance +/- 0.01	
6 加工 100	
7.Specification 加工 OEM service	
8 加工 25-30	
9 加工 accessoried	
10 加工 Austrial EU	
11. 加工 ISO 9001	
加工	
1 加工 ISO 10	
2 加工	
3 surface finishment kinds available	
4 加工	
5 加工	
6 加工	
7 加工	
加工	
加工 加工	
加工 加工	
加工 ISO9001	
加工 加工	
加工 OEM	

Safety is our serious job for our worker and engineer team

