

Inspection Report

Report No.: XYL-150719
 Supplier : XY-GLOBAL

Inspection Date: 3th Sep, 2015
 Inspector: Leo

Inspection only for: PO . XYL-150719 Item No. XY11LM019	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM019	11000PCS	1% inspection	Opcs	No failure	11000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	部品 部品名OEM部品
仕様	ADC12 A380
材質	部品名
加工	加工方法
公差	公差
表面	CNC 加工
MOQ	MOQ
公差	+/- 0.01
公差	T / T 50
公差	CNC 加工
公差	公差
公差	公差
公差	20 25 T / T 50
公差	公差
1.Name 部品名OEM部品	
2.Process 加工方法CNC	
3.Material 部品ADC12 A380	
4.Surface 表面処理	
5.Tolerance +/- 0.01	
6.公差 100	
7.Specification 部品名OEM service	
8.公差 25-30	
9.公差 accessoried	
10.公差 Austrial EU	
11.公差 ISO 9001	
公差	
1. ISO 10	
2. 公差	
3. sureface finishment kinds available	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
公差	
公差 公差	
公差 公差	
公差 ISO9001	
公差 公差	
公差 OEM	

Safety is our serious job for our worker and engineer team

