

**Inspection Report**

Report No.: XYSJ-140704  
Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup> Aug, 2014  
Inspector: Leo

Inspection only for: PO . XYSJ-140704 Item No. XY11KA002	<b>Inspection Result:</b> <b>PASS</b>
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA002	26000PCS	5% inspection	0pcs	No failure	26000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing 2. Product



3. Product 4 Product

	<table border="1"> <tr><th colspan="7">[3] 3-10</th></tr> <tr><td>M</td><td>39.510</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td></tr> <tr><td>L</td><td>195.100</td><td>0.005</td><td>0.005</td><td>0.005</td><td>195.100</td><td>0.005</td></tr> <tr><td>T</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> <tr><td>D</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> </table>	[3] 3-10							M	39.510	0.015	0.015	0.015	0.015	0.015	L	195.100	0.005	0.005	0.005	195.100	0.005	T	0.005	0.005	0.005	0.005	0.005	0.005	D	0.005	0.005	0.005	0.005	0.005	0.005
	[3] 3-10																																			
	M	39.510	0.015	0.015	0.015	0.015	0.015																													
	L	195.100	0.005	0.005	0.005	195.100	0.005																													
	T	0.005	0.005	0.005	0.005	0.005	0.005																													
D	0.005	0.005	0.005	0.005	0.005	0.005																														
<table border="1"> <tr><th colspan="7">[3] 3-11</th></tr> <tr><td>M</td><td>39.510</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td></tr> <tr><td>L</td><td>195.100</td><td>0.005</td><td>0.005</td><td>195.100</td><td>0.005</td><td>0.005</td></tr> <tr><td>T</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> <tr><td>D</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> </table>	[3] 3-11							M	39.510	0.015	0.015	0.015	0.015	0.015	L	195.100	0.005	0.005	195.100	0.005	0.005	T	0.005	0.005	0.005	0.005	0.005	0.005	D	0.005	0.005	0.005	0.005	0.005	0.005	
[3] 3-11																																				
M	39.510	0.015	0.015	0.015	0.015	0.015																														
L	195.100	0.005	0.005	195.100	0.005	0.005																														
T	0.005	0.005	0.005	0.005	0.005	0.005																														
D	0.005	0.005	0.005	0.005	0.005	0.005																														
<table border="1"> <tr><th colspan="7">[3] 3-12</th></tr> <tr><td>M</td><td>39.510</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td></tr> <tr><td>L</td><td>195.100</td><td>0.005</td><td>0.005</td><td>195.100</td><td>0.005</td><td>0.005</td></tr> <tr><td>T</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> <tr><td>D</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> </table>	[3] 3-12							M	39.510	0.015	0.015	0.015	0.015	0.015	L	195.100	0.005	0.005	195.100	0.005	0.005	T	0.005	0.005	0.005	0.005	0.005	0.005	D	0.005	0.005	0.005	0.005	0.005	0.005	
[3] 3-12																																				
M	39.510	0.015	0.015	0.015	0.015	0.015																														
L	195.100	0.005	0.005	195.100	0.005	0.005																														
T	0.005	0.005	0.005	0.005	0.005	0.005																														
D	0.005	0.005	0.005	0.005	0.005	0.005																														
<table border="1"> <tr><th colspan="7">[3] 3-13</th></tr> <tr><td>M</td><td>39.510</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td></tr> <tr><td>L</td><td>195.100</td><td>0.005</td><td>0.005</td><td>195.100</td><td>0.005</td><td>0.005</td></tr> <tr><td>T</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> <tr><td>D</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> </table>	[3] 3-13							M	39.510	0.015	0.015	0.015	0.015	0.015	L	195.100	0.005	0.005	195.100	0.005	0.005	T	0.005	0.005	0.005	0.005	0.005	0.005	D	0.005	0.005	0.005	0.005	0.005	0.005	
[3] 3-13																																				
M	39.510	0.015	0.015	0.015	0.015	0.015																														
L	195.100	0.005	0.005	195.100	0.005	0.005																														
T	0.005	0.005	0.005	0.005	0.005	0.005																														
D	0.005	0.005	0.005	0.005	0.005	0.005																														
<table border="1"> <tr><th colspan="7">[3] 3-14</th></tr> <tr><td>M</td><td>39.510</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td><td>0.015</td></tr> <tr><td>L</td><td>195.100</td><td>0.005</td><td>0.005</td><td>195.100</td><td>0.005</td><td>0.005</td></tr> <tr><td>T</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> <tr><td>D</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td><td>0.005</td></tr> </table>	[3] 3-14							M	39.510	0.015	0.015	0.015	0.015	0.015	L	195.100	0.005	0.005	195.100	0.005	0.005	T	0.005	0.005	0.005	0.005	0.005	0.005	D	0.005	0.005	0.005	0.005	0.005	0.005	
[3] 3-14																																				
M	39.510	0.015	0.015	0.015	0.015	0.015																														
L	195.100	0.005	0.005	195.100	0.005	0.005																														
T	0.005	0.005	0.005	0.005	0.005	0.005																														
D	0.005	0.005	0.005	0.005	0.005	0.005																														

5. Product: 6. The test report



Safety is our serious job for our worker and engineer team

