

**Inspection Report**

Report No.: XYSL-140621  
 Supplier : XY-GLOBAL

Inspection Date: 25<sup>th</sup> Jul, 2014  
 Inspector: Leo

Inspection only for: PO . XYSL-140621 Item No. XY11WD043	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11WD043	10000PCS	5% inspection	0pcs	No failure	10000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



