

Inspection Report

Report No.: XYA-130205
 Supplier : XY-GLOBAL

Inspection Date: 24th Apr., 2013
 Inspector:KEN

Inspection only for: Item No: CA241-0208	Inspection Result: PASS
---	----------------------------

Description	Finished Qty	Sample Size	Defect Found	Defects Description	Acceptable Qty
CA241-0208	320000 PCS	500PCS	5pcs	No failure, with little flaws, acceptable	320000pcs

Appearance Inspection :
 5pcs burrs and scratch on products surface, acceptable

Dimension Inspection:
 No failure , refer to measurement report.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample is 100% inspection.

Digital photo records :

	
1. Packing	2. Packing
	
3. Packing	4. Packing
	
5. Product	6. Product
	
7. Product	8. Product
	
9. Inspection	10. Inspection
	
11. Inspection	12. Inspection

品名	铝合金 精密加工零件
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 POM
规格	按图
数量	按图
公差	按图
表面处理	CNC 阳极氧化 喷砂 抛光 电镀 喷漆
MOQ	按图
交期	+/-0.01
包装	T / T 前50% 后50% T / T; 按图
加工	CNC 车削 cnc 铣削 cnc 钻孔 cnc 磨削 抛光 喷砂 阳极氧化
精度	按图 公差 cnc 加工
交期	按图
数量	20-25 件 T / T 50 件
公差	按图
1. Name 铝合金 OEM cnc 零件	
2. 铝合金 cnc 零件	
3. 材料 AL6061 AL6065 AL6063 AL7075 POM	
4. 公差 +/- 0.01mm	
数量 100 件	
7. OEM 加工	
8. 交期 25-30 天	
9. cnc 加工	
10. 表面处理	
11. 按图 ISO 9001	
按图	
1. 10 件 ISO 9001	
按图	
按图	
按图	
按图	
按图	
7. 按图	
按图	
按图	
按图 ISO 9001	
按图	
按图 OEM 加工	
按图	