

LED

**Inspection Report**

**Report No.:** XYS-130729  
**Supplier :** XY-GLOBAL

**Inspection Date:** 25<sup>th</sup> Aug, 2013  
**Inspector:** Leo

Inspection only for: PO . XYS-130729 Item No.XY-100041	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-9921300	3000PCS	5% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

