

XYElectronics Technology Co., Ltd

## In spection Report

Report No.:XYS-130503 InspectionDate:15<sup>th</sup>-Jun, 2013

Supplier: XY-GLOBAL Inspector: Leo

Inspection only for:	Inspection Result:
PO . XYS-130503 Item No.XY-1300185	PASS


Description	Finished Q'ty	Sample Size	Defect Found	II IGTACTS I IGSCRINTION	Acceptable Q'ty
XY-1300185	100PCS	100% inspection	0pcs	No failure	100pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary

The inspection sample plan is 100% inspection.







6. Product:

5. Product:

5.Tolerance: can reach to +/-0.01mm
6.Quality control: 100% inspected
7.Specification: OEM serice, strictly per drawing and samples
8. Sample delivery time: 25-30 days, per products.
9. Application: aluminum die casting parts,mining accessories, machinery accessoried, auto parts etc.
10. Customer: USA,Canada, Austrial, EU etc.
11. Certification: ISO 9001

Our Advantage
1. 10 years experience with ISO certified
2. All kinds of material is available
3. All kindls of sureface finishment is abailable
4. High quality with competitive price
5. Fast delivery time
6. Sample available
7. Have export experience to all over the world
Our Services

Aluminum die casting parts sample: Can supply for test Aluminum die casting parts packing: Standard packing Aluminum die casting parts certification: ISO9001

Aluminum die casting parts quality: Strictly quality control

Aluminum die casting parts OEM is welcomed