



Inspection Report

Report No.: XYF-130806  
 Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> Sep-, 2013  
 Inspector: LEO

Inspection only for: PO . XYK-130806      Item No.200-140097	<b>Inspection Result:</b> PASS
-----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-140097	20000Set	100% inspection	0pcs	No failure	20000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.


Digital photo records :



1. Packing      2. Product:



3. Product:      4. Product:



5. Product :      6. inspection reports

