

Inspection Report

Report No.: XYD-131017
Supplier : XY-GLOBAL

Inspection Date:15th Nov-, 2013
Inspector:ALEX

Inspection only for: PO . XYD-131017 Item No.XY-MST-080	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-MST-080	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

