

Inspection Report

Report No.: XYSJ-140716
 Supplier : XY-GLOBAL

Inspection Date: 25th Aug, 2014
 Inspector: Leo

Inspection only for: PO . XYSJ-140716 Item No. XY11KA012	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA012	33000PCS	5% inspection	0pcs	No failure	33000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product	6. The test report

Safety is our serious job for our worker and engineer team

