

□□□□ □□□□ AL 6061



Inspection Report

Report No.: XYK-130803
Supplier : XY-GLOBAL







Inspection Date:06th- Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130803 Item No.1305970	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300098	2000PCS	3% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

