

Inspection Report







Report No.: XYFA-130802
 Supplier : XY-GLOBAL

Inspection Date: 1st Sep-, 2013
 Inspector: LEO

Inspection only for: PO . XYFA-130802 Item No.400-01-056	Inspection Result: PASS
----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-056	100000pcs	100% inspection	0pcs	No failure	100000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

