

Inspection Report

Report No.: XYLA-150303
 Supplier : XY-GLOBAL

Inspection Date: 10th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150303 Item No. XY31PC002	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC003	20000PCS	1% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Safety is our serious job for our worker and engineer team

