

Inspection Report

Report No.: XYF-130822
Supplier : XY-GLOBAL

Inspection Date: 17th- Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYF-130822 Item No. 200-30-256	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-30-256	10000Set	100% inspection	0pcs	No failure	10000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing

2. Product:



3. Product:

4. Product:



5. Product :

6. inspection reports

