

Inspection Report

Report No.: XYFA-140902
 Supplier : XY-GLOBAL

Inspection Date: 2th Oct., 2014
 Inspector: LEO

Inspection only for: PO . XYBA-140902 Item No. XY21ZC059	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC059	3800pcs	7% inspection	0pcs	No failure	3800pcs







Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

