

Inspection Report

Report No.: XYDA-150322
 Supplier : XY-GLOBAL

Inspection Date: 15th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYDA-150322 Item No. XY31CY038	Inspection Result: PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY038	55000PCS	1% inspection	0pcs	No failure	55000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. report</p>

