

**Inspection Report**

Report No.: XYKS-140612  
 Supplier : XY-GLOBAL

Inspection Date: 10<sup>th</sup> July, 2014  
 Inspector: Leo

Inspection only for: PO . XYSK-140612 Item No. XY31SY56	<u>Inspection Result:</u> <b>PASS</b>
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY56	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :



<b>1. Packing</b>	<b>2. Product</b>
<b>3. Product</b>	<b>4 Product</b>
<b>5. Product:</b>	<b>6. report</b>



Safety is our serious job for our worker and engineer team

