

Inspection Report

Report No.: XYKS-140608
 Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140608 Item No. XY31SY52	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY52	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :										
										
1. Packing	2. Product									
										
3. Product	4 Product									
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <p>XY Electronics Technology Co., Ltd Inspection Report</p> <table border="1"> <tr> <td>Client: XY Electronics Technology Co., Ltd</td> <td>Product Name: XY31SY52</td> <td>Inspection Date: 2014.07.05</td> </tr> <tr> <td>Part No: XY31SY52</td> <td>Lot No: XY31SY52</td> <td>Inspector: Leo</td> </tr> <tr> <td>Quantity: 12000</td> <td>Sample Size: 120</td> <td>Defect Found: 0</td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspector: Leo</p> <p>Date: 2014.07.05</p>	Client: XY Electronics Technology Co., Ltd	Product Name: XY31SY52	Inspection Date: 2014.07.05	Part No: XY31SY52	Lot No: XY31SY52	Inspector: Leo	Quantity: 12000	Sample Size: 120	Defect Found: 0
Client: XY Electronics Technology Co., Ltd	Product Name: XY31SY52	Inspection Date: 2014.07.05								
Part No: XY31SY52	Lot No: XY31SY52	Inspector: Leo								
Quantity: 12000	Sample Size: 120	Defect Found: 0								
5. Product:	6. report									

Safety is our serious job for our worker and engineer team

