

Inspection Report

Report No.: XYK-131019
 Supplier : XY-GLOBAL

Inspection Date: 14th Nov-, 2013
 Inspector: ALEX

| | |
|---|----------------------------|
| Inspection only for: PO . XYK-131019 Item No.XY-CT-D-048 | Inspection Result: PASS |
|---|----------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|-----------------|--------------|---------------------|-----------------|
| XY-CT-D-048 | 10000PCS | 0.1% inspection | 0pcs | No failure | 10000pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

| | |
|---|--|
| Digital photo records : | |
|  |  |
| 1. Packing | 2. Product: |
|  |  |
| 3. Product: | 4. Product: |
|  |  |
| 5. Product : | 6. Product: |

