

Inspection Report

Report No.: XYGA-150310
 Supplier : XY-GLOBAL

Inspection Date: 15th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140310 Item No. XY21ZC050	Inspection Result: PASS
----------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC050	5000pcs	7% inspection	Opes	No failure	5000pcs







Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

