

Inspection Report

Report No.: XYLA-150313
 Supplier : XY-GLOBAL






Inspection Date: 18th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150313 Item No. XY31PC009	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC009	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Safety is our serious job for our worker and engineer team

