

Inspection Report

Report No.: XYDA-150313
Supplier : XY-GLOBAL

Inspection Date: 8th Apr, 2015
Inspector: Leo

Inspection only for: PO . XYDA-150313 Item No. XY31CY031	Inspection Result: PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY031	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



5. Product: 6. report

XY-GLOBAL 深圳市真朴电子科技有限公司
XY Electronics Technology Co., Ltd

Product Name: XY31CY031
Product Type: XY31CY031
Inspection Date: 2015-04-08
Inspector: Leo

Item No.	Item Name	Unit	Quantity	Defect	Defect Description
1	XY31CY031	PCS	35000	0	

Inspector: Leo
Date: 2015-04-08

