

Inspection Report

Report No.: XYBA-140904
Supplier : XY-GLOBAL

Inspection Date: 1th Oct, 2014
Inspector: LEO

Inspection only for: PO . XYBA-140904 Item No. XY21ZC003	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC003	600PCS	7% inspection	0pcs	No failure	600pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	鋁合金 CNC 加工零件 CNC 加工零件 CNC 加工零件
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316 不銹鋼
規格	依照圖紙
加工方法	CNC 加工
表面處理	噴砂 噴漆 拋光 氧化
公差	±0.01MM
品質	100%
交期	20-25 天
備註	
1.Name:	OEM 零件
2.Process:	CNC 加工
3.Material:	AL6061 AL6065 AL6063 AL7075 POM
4.Surface:	噴砂 噴漆 拋光 氧化
5.Tolerance:	0.01 -/+ 公差
6.Quality:	100%
7.Specification:	OEM 規格
8.	30-25 天
9.	accessoried 零件
10.	AUSTRIAL 零件
11.	ISO 9001
1.	10 種
2.	表面處理
3.	surface finishment available
4.	加工方法
5.	公差
6.	品質
7.	交期
CNC	加工
CNC	加工
CNC	ISO9001
CNC	加工
	OEM