

Inspection Report

Report No.: XYDA-150315
 Supplier : XY-GLOBAL

Inspection Date: 8th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYDA-150315 Item No. XY31CY033	Inspection Result: PASS
---	----------------------------



Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY033	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :




1. Packing	2. Product
------------	------------

3. Product	4 Product
------------	-----------





5. Product:	6. report
-------------	-----------

