

Inspection Report

Report No.: XYAN-150302
 Supplier : XY-GLOBAL

Inspection Date: 1th Apr-, 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150302 Item No. XY21ZC088	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC088	6800pcs	7% inspection	0pcs	No failure	6800pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

Safety is our serious job for our worker and engineer team

