

Inspection Report

Report No.: XYI-140302
 Supplier : XY-GLOBAL









Inspection Date: 5th Apr, 2014
 Inspector: Leo

Inspection only for: PO . XYI-140302 Item No.140110	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
140110	50000PCS	1% inspection	0pcs	No failure	50000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:
	
7. Product:	8. Report:

