

**Inspection Report**

Report No.: XYL-150727  
 Supplier : XY-GLOBAL

Inspection Date: 14<sup>th</sup> Sep, 2015  
 Inspector: Leo

Inspection only for: PO . XYL-150727 Item No. XY11LM027	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11LM027	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product</p> 
<p>3. Product</p> 	<p>4 Product</p> 
<p>5. Product:</p>	<p>6. Report:</p>

ชื่อผลิตภัณฑ์	เซ็นเซอร์อุณหภูมิแบบดิจิตอล 12bit ADC12bit A380
หมายเลข	ADC12 A380
ชื่อผู้ผลิต	...
ชื่อรุ่น	...
ชื่อวัสดุ	...
ชื่อผิวสัมผัส	...
ชื่อประเภท	...
ชื่อสี	...
ชื่อสี / รหัสสี	+/- 0.01MM
ชื่อผิวสัมผัส	T / T 50 ...
ชื่อประเภท	...
ชื่อวัสดุ	...
ชื่อผิวสัมผัส	20-25 ...
ชื่อประเภท	...
1. Name:	...
2. Process:	...
3. Material:	ADC12 A380
4. Surface	...
5. Tolerance:	0.01 -/+ ...MM
6. Quality	...
7. Specification:	OEM ...
8.	...
9.	accessoried ...
10.	AUSTRIAL ...
11.	ISO 9001
ชื่อวัสดุ	...
1. 10	...
2.	...
3.	kindls ... finishment ... available
4.	...
5.	...
6.	...
7.	...
ชื่อผิวสัมผัส	...
ชื่อประเภท	...
ชื่อวัสดุ	...
ชื่อผิวสัมผัส	ISO9001
ชื่อประเภท	...
ชื่อวัสดุ	OEM ...

Safety is our serious job for our worker and engineer team

