

**Inspection Report**

Report No.: XYSL-150723  
 Supplier : XY-GLOBAL







Inspection Date: 25<sup>th</sup> Aug, 2015  
 Inspector: Leo

Inspection only for: PO . XYSL-150723 Item No. XY31XL043	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL043	13000PCS	1% inspection	Opcs	No failure	13000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report



Safety is our serious job for our worker and engineer team

