



**XY Electronics Technology Co., Ltd**

**Inspection Report**

**Report No.:** XYF-130809  
**Supplier :** XY-GLOBAL

**Inspection Date:**3<sup>th</sup> Sep-, 2013  
**Inspector:**LEO

Inspection only for: PO . XYF-130809      Item No.200-40-140	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
200-40-140	15000Set	100% inspection	0pcs	No failure	15000Set

**Appearance Inspection :**  
No failure,

**Dimension Inspection:**  
No failure , below measurement report for reference.

**Assembly Test:**  
No failure

**Inspection Summary**  
The inspection sample plan is 100% inspection.

**Digital photo records :**

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. inspection reports

วัสดุ	อลูมิเนียม 6061 6065 6063 7075 SUS304 SUS303 SUS316
สี	สีเงิน
ความแม่นยำ	+/- 0.01MM
ประเภท	50 มม
คุณสมบัติ	100%
มาตรฐาน	ISO 9001
การรับประกัน	1 ปี
การขนส่ง	โดย DHL / FedEx
การชำระเงิน	บัตรเครดิต / บัตรเดบิต / โอน
การติดต่อ	โทร 02-123-45678
เว็บไซต์	www.example.com
ที่ตั้ง	123 Street, New York
อีเมล	info@example.com
ชื่อ	Example CNC
ประเภท	โรงงาน
การรับประกัน	1 ปี
การขนส่ง	โดย DHL / FedEx
การชำระเงิน	บัตรเครดิต / บัตรเดบิต / โอน
การติดต่อ	โทร 02-123-45678
เว็บไซต์	www.example.com
ที่ตั้ง	123 Street, New York
อีเมล	info@example.com
ชื่อ	Example CNC
ประเภท	โรงงาน
การรับประกัน	1 ปี
การขนส่ง	โดย DHL / FedEx
การชำระเงิน	บัตรเครดิต / บัตรเดบิต / โอน
การติดต่อ	โทร 02-123-45678
เว็บไซต์	www.example.com
ที่ตั้ง	123 Street, New York
อีเมล	info@example.com
ชื่อ	Example CNC
ประเภท	โรงงาน